

AEROSPACE INFORMATION REPORT

**SAE** AIR1537

REV. A

Issued 1977-10 Revised 1996-08

Submitted for recognition as an American National Standard

### REPORT ON AIRCRAFT ENGINE CONTAINMENT

#### INTRODUCTION AND BACKGROUND

On April 23, 1973 the Safety Standardization Advisory Committee of the SAE Aerospace Council requested the Propulsion Division to initiate a technical study of aircraft gas turbine non-containment. This request was reviewed with the Aerospace Council and the Propulsion Division was directed to establish an Ad Hoc Committee.

The committee was established on May 5, 1975 and a preliminary work statement was drafted. The first meeting of the committee was held on July 31, 1975 and the work statement was agreed to as follows:

Committee Representation: The Committee shall be composed of individuals competent and authoritative in the fields of airline operation, airframe and engine design, and able to make significant contributions to this study.

Committee Report: The Committee is to release the results of the study to the SAE Aerospace Council after approval of the Aerospace Propulsion Division. The Committee shall submit its report January 31, 1977 to the Propulsion Division. An extension may be granted by the Propulsion Division if required.

The committee decided that commercial helicopter operations were so small, in comparison to fixed wing aircraft operations, that their inclusion in this study was not warranted. General aviation was not considered as it was beyond the scope of this committee.

Committee Membership and Activity: As stated in the Statement of Work for the committee: "The committee shall be composed of individuals competent and authoritative in the fields of airline operation, airframe and engine design, and able to make significant contributions to this study."

The individuals forming the committee were selected from companies in the fields of airline operation (Pan American, Trans-World and United), airframe design (Beech, Boeing, Lockheed and McDonnell Douglas), engine design (AiResearch, Allison, General Electric, Pratt & Whitney, and Rolls-Royce), and the FAA.

SAE Technical Standards Board Rules provide that: "This report is published by SAE to advance the state of technical and engineering sciences. The use of this report is entirely voluntary, and its applicability and suitability for any particular use, including any patent infringement arising therefrom, is the sole responsibility of the user."

SAE reviews each technical report at least every five years at which time it may be reaffirmed, revised, or cancelled. SAE invites your written comments and suggestions.

Copyright 1996 Society of Automotive Engineers, Inc. All rights reserved.

Printed in U.S.A.

### SAE AIR1537 Revision A

# INTRODUCTION AND BACKGROUND (Continued)

The committee established a schedule of meetings consistent with the submission of the report to the Propulsion Division in January 1977. The submission of the final report was moved to May 1977 by the SAE Aerospace Council. Nine meetings were held between July 31, 1975 and February 1977.

## **TABLE OF CONTENTS**

	INTRODUCTION AND BACKGROUND	1	
1.	SCOPE	4	
1.1	Purpose		
2.	SUMMARY	4	
3.	CONCLUSIONS, OBSERVATIONS, AND RECOMMENDATIONS		
3.1 3.2 3.3	Conclusions Observations Recommendations	5	
4.	DEFINITIONS	6	
4.1 4.2	Definition of Non-Containment  Definition of Aircraft Damage		
5.	ANALYSIS OF DATA	8	
5.1 5.2 5.3 5.3. 5.3. 5.3. 5.4 6.	2 Causes of Rotor Failures	8 9 9 9 9	
6.1 6.2	TablesFigures		

## **SAE AIR1537 Revision A**

# TABLE OF CONTENTS (Continued)

7.	7. POTENTIAL FOR IMPROVEMENT2				
7.1	Engine De	ngine Design26			
7.2	Aircraft De	esign29			
7.3	Increased	Containment Capability30			
APPENDIX A		32			
APPENDIX B		SUMMARY OF NON-CONTAINED ROTOR FAILURES FOR COMMERCIAL AIRCRAFT			
		JANUARY 1962 - DECEMBER 1975			
FIGURE 1		Non-Contained Failures - Disks, Spacers, and Blades21			
FIGURE 1A		Non-Contained Turboprop Failures - Disks, Spacers, and Blades21			
FIGURE 1B		Non-Contained Turbojet Failures - Disks, Spacers, and Blades			
FIGURE 1C		Non-Contained Low-Bypass Turbofan Failures - Disks, Spacers, and Blades22			
FIGUE		Non-Contained High-Bypass Turbofan Failures - Disks, Spacers, and Blades23			
FIGURE 2		Non-Contained Failures by Severity Category			
FIGURE 3 FIGURE 4		Total Aircraft Accidents, Hull Losses, and Fatalities Where Engine			
11001	( )	Non-Containment was Involved			
TABLE 1		Non-Contained Failure Summary			
TABLI	Ε2	Non-Contained Failures Classified by Fragment Type			
TABLE 3		Non-Contained Failures - Disks, Spacers, and Blades			
		Classified by Flight Mode12			
TABLE 4		Non-Contained Failures - Disks, Spacers, and Blades Classified by Cause			
TABLI	= 4A	Non-Contained Failures - Disks and Spacers			
17(02)	_	Classified by Cause14			
TABLI	E 4B	Non-Contained Failures - Blades Only			
		Classified by Cause			
TABLE 5		Non-Contained Failures - Disks, Spacers, and Blades			
TABLE 5A		Classified by Cause (Severity Categories 3 and 4)			
IADLE JA		Classified by Cause (Severity Categories 3 and 4)			
TABLE 5B		Non-Contained Failures - Blades Only			
		Classified by Cause (Severity Categories 3 and 4)			