
**Workplace air — Guidance for the
measurement of respirable crystalline
silica**

*Air des lieux de travail — Lignes directrices pour le mesurage de la
fraction alvéolaire de la silice cristalline*



PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.



COPYRIGHT PROTECTED DOCUMENT

© ISO 2009

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
Introduction.....	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
3.1 General definitions	2
3.2 Sampling definitions	3
3.3 Analytical definitions	3
3.4 Statistical terms	4
4 Principle.....	5
5 Analytical quality requirements	6
6 Administrative controls	6
7 Sampling.....	8
7.1 General	8
7.2 Sampler.....	8
7.3 Filters and foams	8
7.4 Sampling pumps.....	9
7.5 Respirable size selectors.....	9
7.6 Transportation	9
8 Procedures	9
8.1 Handling of filter cassettes.....	9
8.2 Method validation	10
8.3 Calibration	10
8.4 Sample preparation	11
8.5 Sample measurement	11
8.6 Instrumental variation	12
9 Internal quality control.....	13
10 External verification and assessment of uncertainty	13
11 Test report.....	14
11.1 Minimum report requirements.....	14
11.2 Data to be archived by the laboratory	14
Annex A (informative) Polymorphs of crystalline silica and their interferences.....	15
Annex B (informative) The quantification of cristobalite using X-ray diffraction.....	21
Annex C (informative) Example of quality control charting for respirable crystalline silica	24
Annex D (informative) Estimation of expanded uncertainty for measurements of respirable crystalline silica.....	25
Bibliography.....	35