

HB

中华人民共和国航空工业标准

HB 7308~7317-96







过盈螺纹机用和手用丝锥




1996-09-13 发布

1997-01-01 实施

中国航空工业总公司 批准

目 录

序号	标准号 标记代号 ¹⁾	名 称	简 图	页次
1	HB 7308-96 $\frac{1357}{001\sim 002}$	过盈螺纹机用和手用丝锥 HB 6545-91AG、BG 螺纹用 $d=3\sim 4\text{mm}$ $p=0.5\sim 0.7\text{mm}$		2
2	HB 7309-96 $\frac{1357}{003\sim 008}$	过盈螺纹机用和手用丝锥 HB 6545-91AG、BG 螺纹用 $d=5\sim 10\text{mm}$ $p=0.8\sim 1.5\text{mm}$		4
3	HB 7310-96 $\frac{1357}{009\sim 018}$	过盈螺纹机用和手用丝锥 HB 6545-91AG、BG 螺纹用 $d=12\sim 30\text{mm}$ $p=1.25\sim 1.5\text{mm}$		10
4	HB 7311-96 $\frac{1357}{019\sim 021}$	过盈螺纹机用和手用丝锥 HB 6545-91AG、BG 螺纹用 $d=33\sim 39\text{mm}$ $p=1.5\text{mm}$		20
5	HB 7312-96 $\frac{1357}{022\sim 023}$	过盈螺纹机用和手用丝锥 HB 6545-91AG、BG 螺纹用 $d=42\sim 45\text{mm}$ $p=1.5\text{mm}$		24
6	HB 7313-96 $\frac{1357}{024\sim 029}$	过盈螺纹机用和手用丝锥 HB 6545-91CG、DG 螺纹用 $d=5\sim 10\text{mm}$ $p=0.8\sim 1.5\text{mm}$		26

序号	标准号 标记代号 ¹⁾	名 称	简 图	页次
7	HB 7314-96 <u>1357</u> 030~039	过盈螺纹机用和手用丝锥 HB 6545-91CG、DG 螺纹用 $d=12\sim 30\text{mm}$ $p=1.25\sim 1.5\text{mm}$		32
8	HB 7315-96 <u>1357</u> 040~042	过盈螺纹机用和手用丝锥 HB 6545-91CG、DG 螺纹用 $d=33\sim 39\text{mm}$ $p=1.5\text{mm}$		42
9	HB 7316-96 <u>1357</u> 043~044	过盈螺纹机用和手用丝锥 HB 6545-91CG、DG 螺纹用 $d=42\sim 45\text{mm}$ $p=1.5\text{mm}$		46
10	HB 7317-96	过盈螺纹机用和手用丝锥技术条件		48

1)完整的标记代号见标准。