
**Workplace air — Determination of
hexavalent chromium in airborne
particulate matter — Method by ion
chromatography and spectrophotometric
measurement using diphenyl carbazide**

*Air des lieux de travail — Détermination du chrome hexavalent dans les
particules en suspension dans l'air — Méthode par chromatographie
ionique et détection spectrophotométrique avec diphényl carbazide*



Reference number
ISO 16740:2005(E)

© ISO 2005

PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.

© ISO 2005

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
3.1 General definitions	2
3.2 Particle size fraction definitions	3
3.3 Sampling definitions	3
3.4 Analytical definitions	4
3.5 Statistical terms	5
4 Principle	6
5 Reactions	7
6 Requirement	7
7 Reagents	7
8 Apparatus	10
8.1 Sampling equipment	10
8.2 Laboratory apparatus	12
9 Occupational exposure assessment	15
9.1 General	15
9.2 Personal sampling	15
9.3 Static sampling	16
9.4 Selection of measurement conditions and measurement pattern	16
10 Sampling method	17
10.1 Preliminary considerations	17
10.2 Preparation for sampling	18
10.3 Sampling position	19
10.4 Collection of samples	19
10.5 Transportation	20
11 Analysis	21
11.1 Analytical requirements	21
11.2 Preparation of solutions for determination of soluble hexavalent chromium compounds	22
11.3 Preparation of solutions for determination of insoluble hexavalent chromium compounds	23
11.4 Instrumental analysis	25
11.5 Estimation of detection and quantification limits	27
11.6 Quality control	27
11.7 Measurement uncertainty	28
12 Expression of results	28
13 Method performance	29
13.1 Sample collection and stability	29
13.2 Hotplate extraction	29
13.3 Ultrasonic extraction	29
13.4 Interferences	29
14 Special cases	30
14.1 Spray-painting	30