
**Vacuum gauges — Definitions and
specifications for quadrupole mass
spectrometers**

*Manomètres à vide — Définitions et spécifications des spectromètres
de masse quadripolaires*





COPYRIGHT PROTECTED DOCUMENT

© ISO 2012

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
Introduction	v
1 Scope	1
2 Terms and definitions	1
2.1 Definitions of components	1
2.2 Definitions of physical parameters	5
3 Symbols and abbreviated terms	8
4 Principle of QMS	9
5 Specifications for a QMS to be provided by manufacturers	9
5.1 Mass range	9
5.2 Type of ion source	9
5.3 Type of ion detector	9
5.4 Mass resolution	10
5.5 Mass number stability	10
5.6 Sensitivity	10
5.7 Linear response range	10
5.8 Minimum detectable partial pressure	10
5.9 Minimum detectable concentration	10
5.10 Maximum operational pressure	10
5.11 Scanning parameter	10
5.12 Signal output	11
5.13 Potentials	11
5.14 Detector specifications	11
5.15 Set point	11
5.16 Maximum bake-out temperature	11
5.17 Nominal operating conditions	11
5.18 Warm-up time	11
5.19 Filament material	11
5.20 Electron emission current	11
5.21 Filament exchange	11
5.22 Detector exchange	11
5.23 Fitting to chamber	12
5.24 Mounting orientation	12
5.25 Dimensions	12
5.26 Internal volume	12
5.27 Mass of sensor head and electronic unit	12
5.28 Input power of electronic unit	12
5.29 Cable	12
5.30 Software	12
5.31 Interface	12
5.32 Storage and transportation condition	12
6 Optional specifications for QMS to be provided by manufacturers	13
6.1 Mass resolution	13
6.2 Fragmentation or cracking pattern	13
6.3 Temperature coefficient of sensitivity	13
6.4 QMS sensor cleaning	13
6.5 Degassing	13
6.6 Degassing power	13
6.7 Photographs	13
6.8 Inspection record	13
6.9 Outgassing rate	13
Bibliography	14