
**Non-destructive testing of welds —
Ultrasonic testing — Techniques, testing
levels, and assessment**

*Contrôle non destructif des assemblages soudés — Contrôle par
ultrasons — Techniques, niveaux d'essai et évaluation*



PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.



COPYRIGHT PROTECTED DOCUMENT

© ISO 2010

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
1 Scope	1
2 Normative references	1
3 Symbols and definitions	2
4 Principle	2
5 Information required prior to testing	3
5.1 Items to be specified	3
5.2 Specific information required before testing	3
5.3 Written test procedure	4
6 Requirements for personnel and equipment	4
6.1 Personnel qualifications	4
6.2 Equipment	4
6.3 Probe parameters	4
7 Testing volume	5
8 Preparation of scanning surfaces	5
9 Parent metal testing	6
10 Range and sensitivity setting	7
10.1 General	7
10.2 Reference for sensitivity setting	7
10.3 Evaluation levels	8
10.4 Transfer correction	8
10.5 Signal to noise ratio	8
11 Testing levels	9
12 Testing techniques	9
12.1 General	9
12.2 Manual scan path	9
12.3 Testing for imperfections perpendicular to the testing surface	9
12.4 Location of indications	9
12.5 Evaluation of indications	10
13 Test report	11
Annex A (normative) Testing levels for various types of welded joints	13