
**Surface chemical analysis —
Medium-resolution Auger electron
spectrometers — Calibration of
energy scales for elemental analysis**

*Analyse chimique des surfaces — Spectromètres d'électrons Auger
à résolution moyenne — Étalonnage des échelles d'énergie pour
l'analyse élémentaire*



COPYRIGHT PROTECTED DOCUMENT

© ISO 2016, Published in Switzerland

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Ch. de Blandonnet 8 • CP 401
CH-1214 Vernier, Geneva, Switzerland
Tel. +41 22 749 01 11
Fax +41 22 749 09 47
copyright@iso.org
www.iso.org

Contents

Page

Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and abbreviated terms	1
5 Outline of method	2
6 Energy scale calibration procedures	3
6.1 Obtaining reference samples.....	3
6.2 Mounting samples.....	3
6.3 Cleaning samples.....	3
6.4 Choosing spectrometer settings for energy calibration.....	5
6.5 Operating the instrument.....	5
6.6 Measurement of reference peaks.....	6
6.7 Determining measured kinetic energies of reference peaks.....	7
6.8 Determining correction of instrument kinetic energy scale.....	8
6.9 Next calibration.....	9
Bibliography	11