
**Surface chemical analysis — High-
resolution Auger electron spectrometers —
Calibration of energy scales for elemental
and chemical-state analysis**

*Analyse chimique des surfaces — Spectromètres d'électrons Auger à
haute résolution — Étalonnage des échelles d'énergie pour l'analyse
élémentaire et de l'état chimique*



Reference number
ISO 17974:2002(E)

© ISO 2002

PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.

© ISO 2002

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 0111
Fax + 41 22 749 0947
E-mail copyright@iso.ch
Web www.iso.ch

Printed in Switzerland

Contents

Page

Foreword	iv
Introduction.....	v
1 Scope.....	1
2 Normative reference.....	1
3 Terms and definitions	1
4 Symbols and abbreviated terms.....	2
5 Outline of method.....	3
6 Procedure for calibrating the energy scale	6
6.1 Obtaining reference samples.....	6
6.2 Mounting samples.....	6
6.3 Cleaning samples.....	6
6.4 Choosing spectrometer settings for energy calibration.....	6
6.5 Operating the instrument	7
6.6 Options for initial or subsequent calibration measurements	7
6.7 Measurements for peak kinetic energy repeatability standard deviation and scale linearity.....	8
6.8 Calculating peak kinetic energy repeatability standard deviation.....	10
6.9 Determining relevant reference kinetic energies	12
6.10 Checking kinetic energy scale linearity.....	13
6.11 Procedure for regular calibration error determination.....	14
6.12 Procedures for correction of the instrument kinetic energy scale	15
6.13 Next calibration	17
6.14 Establishing calibration intervals.....	17
Annex A (normative) Maximum number of points for a single application of Savitzky and Golay smoothing of peaks at 0,1 eV energy intervals.....	19
Annex B (normative) Least squares determination of peak kinetic energy by a simple computational method.....	20
Annex C (informative) Derivation of uncertainties	23
Annex D (informative) Citation of uncertainties of measured kinetic energies	25
Bibliography.....	27