

INTERNATIONAL STANDARD ISO 1034-1973 (E)/ERRATUR

R-27-09

Published 1974-03-15

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION-МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ-ORGANISATION INTERNATIONALE DE NORMALISATI

Aircraft — Ground air-conditioning connections

ERRATUM

Figure 1 and figure 2:

Delete the note "Axis parallel the aircraft" and substitute the following :

"Axis either:

- a) parallel with the longitudinal axis of the aircraft or
- b) parallel with the transverse axis of the aircraft, with the face of the connection in an essentially vertical plane."

Figure 2:

In the last line of the paragraph which begins "The bayonet", delete "transverse" and substitute "vertical".

