

---

---

**Radiological protection — X and gamma reference radiation for calibrating dosimeters and doserate meters and for determining their response as a function of photon energy —**

Part 2:

**Dosimetry for radiation protection over the energy ranges from 8 keV to 1,3 MeV and 4 MeV to 9 MeV**

*Radioprotection — Rayonnements X et gamma de référence pour l'étalonnage des dosimètres et des débitmètres, et pour la détermination de leur réponse en fonction de l'énergie des photons —*

*Partie 2: Dosimétrie pour la radioprotection dans les gammes d'énergie de 8 keV à 1,3 MeV et de 4 MeV à 9 MeV*





**COPYRIGHT PROTECTED DOCUMENT**

© ISO 2019

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office  
CP 401 • Ch. de Blandonnet 8  
CH-1214 Vernier, Geneva  
Phone: +41 22 749 01 11  
Fax: +41 22 749 09 47  
Email: [copyright@iso.org](mailto:copyright@iso.org)  
Website: [www.iso.org](http://www.iso.org)

Published in Switzerland

# Contents

	Page
Foreword .....	v
Introduction .....	vi
<b>1 Scope .....</b>	<b>1</b>
<b>2 Normative references .....</b>	<b>2</b>
<b>3 Terms and definitions .....</b>	<b>2</b>
<b>4 Standard instrument .....</b>	<b>3</b>
4.1 General .....	3
4.2 Calibration of the standard instrument .....	3
4.3 Energy dependence of the response of the standard instrument .....	3
<b>5 Conversion from the measured quantity air kerma, <math>K_a</math>, to the required phantom related measuring quantity .....</b>	<b>4</b>
5.1 General .....	4
5.2 Determination of conversion coefficients .....	6
5.2.1 General .....	6
5.2.2 Calculation of conversion coefficients from spectral fluence .....	6
5.3 Validation of reference fields and of listed conversion coefficients using dosimetry .....	7
<b>6 Direct calibration of the reference field in terms of the required phantom related measuring quantity .....</b>	<b>8</b>
<b>7 Measurement procedures applicable to ionization chambers .....</b>	<b>8</b>
7.1 Geometrical conditions .....	8
7.2 Chamber support and stem scatter .....	8
7.3 Location and orientation of the standard chamber .....	8
7.4 Measurement corrections .....	8
7.4.1 General .....	8
7.4.2 Corrections for air temperature, pressure and humidity variation from reference calibration conditions .....	9
7.4.3 Corrections for radiation-induced leakage, including ambient radiation .....	9
7.4.4 Incomplete ion collection .....	10
7.4.5 Beam non-uniformity .....	10
<b>8 Additional procedures and precautions specific to gamma radiation dosimetry using radionuclide sources .....</b>	<b>10</b>
8.1 Use of certified source output .....	10
8.2 Use of electron equilibrium caps .....	10
8.3 Radioactive source decay .....	10
8.4 Radionuclide impurities .....	10
8.5 Interpolation between calibration positions .....	10
<b>9 Additional procedures and precautions specific to X-radiation dosimetry .....</b>	<b>11</b>
9.1 Variation of X-radiation output .....	11
9.2 Monitor .....	11
9.3 Adjustment of air kerma rate .....	11
<b>10 Dosimetry of reference radiation at photon energies between 4 MeV and 9 MeV .....</b>	<b>12</b>
10.1 Dosimetric quantities .....	12
10.2 Measurement of the dosimetric quantities .....	12
10.2.1 General .....	12
10.2.2 Air kerma (rate) .....	13
10.2.3 Phantom related operational quantities $H^*(10)$ , $H_p(10)$ , $H'(3)$ and $H_p(3)$ .....	13
10.3 Measurement geometry .....	13
10.4 Monitor .....	13
10.5 Determination of air kerma (rate) free-in-air .....	14
10.5.1 General .....	14