

BRITISH STANDARD

Sampling procedures for inspection by variables –

**Part 1: Guide to single sampling
plans indexed by acceptance quality
limit (AQL) for lot-by-lot inspection
for a single quality characteristic and
a single AQL**

ICS 03.120.30

BSi
British Standards

Publishing and copyright information

The BSI copyright notice displayed in this document indicates when the document was last issued.

© BSI 2007

ISBN 978 0 580 50163 0

The following BSI references relate to the work on this standard:

Committee reference SS/5

Draft for comment 05/30134582

Publication history

First published as BS 6002, May 1979

First published as BS 6002-1, November 1993

Revised February 2007

Amendments issued since publication

Amd. no.	Date	Text affected
-----------------	-------------	----------------------

Contents

Foreword *v*

Introduction *1*

- 1** Scope *3*
- 2** Normative references *3*
- 3** Terms and definitions *4*
- 4** Symbols *6*
- 5** Acceptance quality limit (AQL) *8*
- 6** Switching rules for normal, tightened and reduced inspection *9*
- 7** Relation to BS 6001-1 *9*
- 8** Limiting quality protection *11*
- 9** Planning *12*
- 10** Choice between variables and attributes *12*
- 11** Choice between the “s” and “ σ ” methods *13*
- 12** Choice of inspection level and AQL *14*
- 13** Choice of sampling plan *14*
- 14** Preliminary operations *15*
- 15** Standard procedure for the “s” method *16*
- 16** Standard procedure for the “ σ ” method *26*
- 17** Procedure during continuing inspection *29*
- 18** Normality and outliers *30*
- 19** Records *30*
- 20** Operation of switching rules *31*
- 21** Discontinuation and resumption of inspection *31*
- 22** Switching between the “s” and “ σ ” methods *32*
- 23** Chart A – Sample size code letters of standard single sampling plans for specified qualities at 95% and 10% probabilities of acceptance *33*
- 24** Charts B to R – Operating characteristic curves and tabulated values for single sampling plans, normal inspection: “s” method *34*
- 25** Charts s-D to s-R – Acceptance curves for combined control of double specifications limits: “s” method *64*

Annexes

- Annex A (normative) Table for determining the sample size code letter *77*
- Annex B (normative) Form *k* “s” method single sampling plans *78*
- Annex C (normative) Form *k* “ σ ” method single sampling plans *81*
- Annex D (normative) Values of f_s for maximum sample standard deviation (MSSD) *84*
- Annex E (normative) Values of f_σ for maximum process standard deviation (MPSD) *87*
- Annex F (normative) Estimating the process fraction nonconforming for sample size 3: “s” method *88*
- Annex G (normative) Type p^* single sampling plans *91*
- Annex H (normative) Values of c_u for upper control limit on the sample standard deviation *92*
- Annex I (normative) Supplementary acceptability constants for qualifying towards reduced inspection *93*
- Annex J (normative) Procedures for obtaining s and σ *94*
- Annex K (informative) Consumer’s risk qualities *96*
- Annex L (informative) Producer’s risks *100*