BS 7644-1: 1993 *Incorporating*

Amendment No. 1

Direct tension indicators —

Part 1: Specification for compressible washers



NO COPYING WITHOUT BSI PERMISSION EXCEPT AS PERMITTED BY COPYRIGHT LAW

Committees responsible for this British Standard

The preparation of this British Standard was entrusted by the General Mechanical Engineering Standards Policy Committee (GME/-) to Technical Committee GME/9, upon which the following bodies were represented:

BEAMA Ltd.

British Constructional Steelwork Association Ltd. British Industrial Fasteners Federation British Railways Board British Steel Industry British Steel Industry (Wire Section) Gauge and Tool Makers' Association Society of Motor Manufacturers and Traders Ltd. Washer Manufacturers' Association of Great Britain

The following bodies were also represented in the drafting of the standard, through subcommittees and panels:

Galvanizers' Association Steel Construction Institute

This British Standard, having been prepared under the direction of the General Mechanical Engineering Standards Policy Committee, was published under the authority of the Standards Board and comes into effect on 15 April 1993

© BSI 03-1999

The following BSI references relate to the work on this standard: Committee reference GME/9 Draft for comment 90/80390 DC

Amendments issued since publication

	Amd. No.	Date	Comments
	7872	August 1993	Indicated by a sideline in the margin
C			
			-

ISBN 0 580 21651 9

Contents

		Page
Cor	nmittees responsible	Inside front cover
For	eword	ii
1	Scope	1
2	References	1
3	Dimensions	1
4	Performance	2
5	Characteristics	4
6	Manufacturer's certificate	4
7	Marking and identification	4
8	Designation	5
Anı	nex A (informative) Use of compressible washer-type direct	,
ten	sion indicators	6
Anı	nex B (informative) Corrosion protection of indicator	
	asuring gap	6
	ure 1 — Dimensions of compressible washer-type direct	
0011	sion indicators	2
~	ure 2 — Bolt tightening by rotation of the nut	
	rmal method of assembly)	3
	ure 3 — Bolt tightening by rotation of the bolt	4
	ernative method of assembly) ure A.1 — Checking the indicator gap	46
		0
	ble 1 — Dimensions of compressible washer-type ect tension indicators	1
	ble 2 — Indicator loads at appropriate gap	1
	ecified in Table 3)	2
. –	ble 3 — Average indicator gaps	3
	ble 4 — Characteristics of indicators	5
	t of references	Inside back cover