

---

---

**Non-destructive testing — Acoustic  
emission testing — Verification of  
the receiving sensitivity spectra  
of piezoelectric acoustic emission  
sensors**

*Essais non destructifs — Contrôle par émission acoustique —  
Vérification des spectres de sensibilité de réception des capteurs  
d'émission acoustique piézoélectriques*





**COPYRIGHT PROTECTED DOCUMENT**

© ISO 2022

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office  
CP 401 • Ch. de Blandonnet 8  
CH-1214 Vernier, Geneva  
Phone: +41 22 749 01 11  
Email: [copyright@iso.org](mailto:copyright@iso.org)  
Website: [www.iso.org](http://www.iso.org)

Published in Switzerland

# Contents

Page

<b>Foreword</b> .....	<b>v</b>
<b>Introduction</b> .....	<b>vi</b>
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms and definitions</b> .....	<b>1</b>
<b>4 Symbols and abbreviated terms</b> .....	<b>3</b>
<b>5 Overview</b> .....	<b>4</b>
5.1 Face-to-face setup — Block diagram.....	4
5.2 Laser vibrometer setup — Block diagram.....	5
<b>6 General requirements related to hardware</b> .....	<b>6</b>
6.1 General.....	6
6.2 Requirements related to the function generator (FG).....	6
6.3 Requirements related to the transmitter.....	7
6.4 Requirements related to the coupling agent between transmitter and sensor under test.....	8
6.5 Requirements related to the sensor-to-transmitter fixing tool.....	8
6.5.1 General.....	8
6.5.2 Requirements.....	8
6.6 Requirements related to the sensor under test (SUT).....	9
6.6.1 General.....	9
6.6.2 Pyroelectric effect.....	9
6.6.3 Integrated pre-amplifier.....	10
6.6.4 Influence of the pre-amplifier input impedance.....	10
6.6.5 Requirements for a list of sensors under test.....	10
6.7 Requirements related to the signal cable from sensor to transient recorder.....	10
6.7.1 General.....	10
6.7.2 Requirement.....	10
6.8 Requirements related to the signal cable from the function generator to the transmitter and to the transient recorder.....	10
6.9 Requirements related to the transient recorder for measuring $U_S$ and $U_F$ .....	11
6.9.1 General.....	11
6.9.2 Input impedance.....	11
6.9.3 Range, resolution, accuracy, sampling rate and buffer length.....	11
6.9.4 Bandwidth.....	12
6.9.5 Trigger settings.....	12
6.9.6 Verification — Calibration.....	12
<b>7 Determination of the receiving sensitivity spectra</b> .....	<b>12</b>
7.1 General.....	12
7.2 Formulae for the determination of receiving sensitivity spectra $R_D$ and $R_V$ .....	12
7.3 Relevant spectra for sensor sensitivity verification.....	13
7.4 Procedure for sensor sensitivity verification.....	14
7.4.1 Preparation.....	14
7.4.2 Cable connections for the face-to-face setup.....	15
7.4.3 Settings of the function generator in the face-to-face setup.....	15
7.4.4 Setting of the transient recorder.....	16
7.4.5 Trial measurement.....	17
7.4.6 Initial crosstalk test.....	18
7.4.7 Capturing data of the sensor under test — Stimulation pulse $U_F$ , sensor response $U_S$ .....	18
7.4.8 Calculating and presenting receiving sensitivity spectra.....	19
7.4.9 Sensor verification report.....	20
7.5 Reproducibility of sensitivity spectra.....	21