



Manufacturers Standardization Society of the Valve and Fittings Industry, Inc.

"The Technical Voice of the Industry for Over 98 Years"

127 Park Street, NE • Vienna, VA 22180-4602 • 703-281-6613 • Fax 703-281-6671 • www.msshq.org • E-mail: standards@msshq.org

EXECUTIVE DIRECTOR: D. E. Thompson

ERRATA SHEET FOR MSS SP-79-2018 (*Socket-Welding Reducer Inserts*)

April 29, 2022

This “normative” errata correction applies to MSS SP-79-2018 edition (current).

NOTE THE FOLLOWING CORRECTIONS (UNDERLINE/STRIKE-THROUGH FORMAT):

- **Page 7, Table 3, *Socket-Welding Reducer Insert Dimensions and Tolerances*.** Correct the data under Type, 6M column for 1½ x 1 row to read as “1” instead of “2”. No other corrections.

This Errata Sheet is intended for those who obtained the Standard Practice before the April 29, 2022 errata publication date indicated above or otherwise do not already have this information. Please include this Errata Sheet within your existing 2018 edition of the Standard Practice.

Future editions of this Standard Practice will include this corrected information.

PRESIDENT: J. E. Barker – DeZURIK, Inc
VICE PRESIDENTS: D. Bayreuther – Neles Corporation • F. J. Washburn – Rexa, Inc.
TREASURER: P. Heald – Bonney Forge Corp.