

## Errata

## NFPA 1983

## Standard on Life Safety Rope and Equipment for Emergency Services

## 2017 Edition

Reference: Various Errata No: 1983-17-2

The Technical Committee on Special operations Protective Clothing and Equipment, and the Correlating Committee on Fire and Emergency Services Protective Clothing and Equipment note the following errors in the 2017 edition of *NFPA 1983*, *Standard on Life Safety Rope and Equipment for Emergency Services*.

- Delete words and cross reference in 5.23.1.10 that refer to a deleted section as follows:
   5.23.1.10 In addition to the compliance and information statements in 5.23.1.9, and 5.23.1.10 at least the following information shall also be printed on the product label(s) where all letters shall be at least 2 mm (5/64 in.) high.:

   (1) Manufacturer's name,...
- 2. Renumber 5.23.1.12 as 5.23.1.11.
- 3. Delete words and cross reference in 5.24.1.10 that refer to a deleted section as follows:
  5.24.1.10-11 In addition to the compliance and information-statements in 5.24.1.9 and 5.24.1.10, at least the following information shall also be printed on the product label(s) where all letters shall be at least 2 mm (5/64 in.) high:
  (1) Manufacturer's name,...
- 4. Renumber 5.24.1.12 as 5.24.1.11.

Issue Date: April 25, 2017

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see <a href="https://www.nfpa.org/docinfo">www.nfpa.org/docinfo</a>)

Copyright © 2017 All Rights Reserved NATIONAL FIRE PROTECTION ASSOCIATION