

INTERNATIONAL  
STANDARD

ISO  
**9827**

First edition  
1994-06-15

---

---

---

**Measurement of liquid flow in open  
channels by weirs and flumes —  
Streamlined triangular profile weirs**

*Mesure de débit des liquides dans les canaux découverts au moyen de  
déversoirs et de canaux jaugeurs — Déversoirs carénés à seuil à profil  
triangulaire*



Reference number  
ISO 9827:1994(E)

## Contents

	Page
<b>1 Scope .....</b>	<b>1</b>
<b>2 Normative references .....</b>	<b>1</b>
<b>3 Definitions .....</b>	<b>1</b>
<b>4 Units of measurement .....</b>	<b>1</b>
<b>5 General requirements .....</b>	<b>1</b>
<b>5.1 Site selection .....</b>	<b>1</b>
<b>5.2 Installation conditions .....</b>	<b>2</b>
<b>6 Maintenance .....</b>	<b>3</b>
<b>7 Measurement of head .....</b>	<b>3</b>
<b>7.1 General .....</b>	<b>3</b>
<b>7.2 Stilling or float well .....</b>	<b>3</b>
<b>7.3 Zero setting .....</b>	<b>3</b>
<b>8 Streamlined triangular profile weirs .....</b>	<b>4</b>
<b>8.1 Specification for a standard weir .....</b>	<b>4</b>
<b>8.2 Location of head measurement section .....</b>	<b>4</b>
<b>8.3 Location of tail water level measurement section .....</b>	<b>4</b>
<b>8.4 Conditions for modular flow .....</b>	<b>4</b>
<b>9 Discharge calculation .....</b>	<b>4</b>
<b>9.1 Discharge equation .....</b>	<b>4</b>
<b>9.2 Coefficients .....</b>	<b>6</b>
<b>9.3 Limitations .....</b>	<b>11</b>
<b>9.4 Uncertainty of measurement .....</b>	<b>11</b>
<b>10 Uncertainties in flow measurement .....</b>	<b>11</b>
<b>10.1 General .....</b>	<b>11</b>
<b>10.2 Sources of error .....</b>	<b>11</b>

© ISO 1994

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization  
Case Postale 56 • CH-1211 Genève 20 • Switzerland

Printed in Switzerland

<b>10.3</b>	<b>Kinds of error .....</b>	<b>12</b>
<b>10.4</b>	<b>Uncertainties in values of coefficients <math>C</math> and <math>C_{dr}</math> .....</b>	<b>12</b>
<b>10.5</b>	<b>Uncertainties in measurements made by the user .....</b>	<b>12</b>
<b>10.6</b>	<b>Combination of uncertainties .....</b>	<b>13</b>
<b>10.7</b>	<b>Presentation of results .....</b>	<b>13</b>
<b>11</b>	<b>Example .....</b>	<b>13</b>