
**Workplace air — Determination
of lithium hydroxide, sodium
hydroxide, potassium hydroxide
and calcium dihydroxide — Method
by measurement of corresponding
cations by suppressed ion
chromatography**

Air des lieux de travail — Détermination de la teneur en hydroxyde de lithium, hydroxyde de sodium, hydroxyde de potassium et dihydroxyde de calcium — Méthode par mesurage des cations correspondants par chromatographie ionique





COPYRIGHT PROTECTED DOCUMENT

© ISO 2013

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
3.1 General definitions.....	2
3.2 Particle size fraction definitions.....	3
3.3 Sampling definitions.....	3
3.4 Analytical definitions.....	4
3.5 Statistical terms.....	6
4 Principle	7
5 Requirement	7
6 Reagents	8
7 Apparatus	9
7.1 Sampling equipment.....	9
7.2 Laboratory apparatus.....	10
8 Occupational exposure assessment	11
8.1 General.....	11
8.2 Personal sampling.....	11
8.3 Static sampling.....	12
8.4 Selection of measurement conditions and measurement pattern.....	12
9 Sampling	13
9.1 Preliminary considerations.....	13
9.2 Preparation for sampling.....	15
9.3 Sampling position.....	15
9.4 Collection of samples.....	16
9.5 Transportation.....	16
10 Analysis	16
10.1 Preparation of test and calibration solutions.....	17
10.2 Instrumental analysis.....	17
10.3 Estimation of detection and quantification limits.....	18
10.4 Quality control.....	19
10.5 Measurement uncertainty.....	20
11 Expression of results	21
12 Method performance	21
12.1 Sampling efficiency and sample storage.....	21
12.2 Quantification limit.....	21
12.3 Upper limits of the working range.....	21
12.4 Bias and precision.....	22
12.5 Uncertainty of sampling and analysis method.....	22
12.6 Interferences.....	22
13 Test report	22
13.1 Test record.....	22
13.2 Laboratory report.....	23
Annex A (informative) Temperature and pressure correction	24
Annex B (normative) Filter materials	25
Annex C (informative) Sampler wall deposits	26