

---

---

**Workplace air — Determination of  
mercury and inorganic mercury  
compounds — Method by cold-vapour  
atomic absorption spectrometry or  
atomic fluorescence spectrometry**

*Air des lieux de travail — Détermination du mercure et des composés  
minéraux de mercure — Méthode par spectrométrie d'absorption  
atomique ou spectrométrie de fluorescence atomique de la vapeur  
froide*



**PDF disclaimer**

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.

© ISO 2004

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office  
Case postale 56 • CH-1211 Geneva 20  
Tel. + 41 22 749 01 11  
Fax + 41 22 749 09 47  
E-mail [copyright@iso.org](mailto:copyright@iso.org)  
Web [www.iso.org](http://www.iso.org)

Published in Switzerland

# Contents

Page

Foreword .....	v
Introduction .....	vi
1 Scope .....	1
2 Normative references .....	1
3 Terms and definitions .....	2
3.1 General definitions .....	2
3.2 Particle size fraction definitions .....	3
3.3 Sampling definitions .....	4
3.4 Analytical definitions .....	5
3.5 Statistical terms .....	6
4 Principle .....	7
5 Interferences .....	8
6 Requirement .....	8
7 Reagents .....	8
8 Apparatus .....	10
8.1 Sampling equipment for diffusive sampling .....	10
8.2 Sampling equipment for pumped sampling .....	11
8.3 Laboratory apparatus .....	14
8.4 Analytical instrumentation .....	15
9 Occupational exposure assessment .....	20
9.1 General .....	20
9.2 Personal sampling .....	20
9.3 Static (area) sampling .....	20
9.4 Selection of measurement conditions and measurement pattern .....	21
10 Sampling .....	22
10.1 Selection of sampling method .....	22
10.2 Consideration of temperature and pressure effects .....	22
10.3 Diffusive sampling .....	23
10.4 Pumped sampling .....	25
11 Analysis .....	29
11.1 General .....	29
11.2 Cleaning of glassware and plasticsware .....	29
11.3 Preparation of blank, sample and calibration solutions for analysis of diffusive badges .....	30
11.4 Preparation of blank, sample and calibration solutions for analysis of pumped samples .....	31
11.5 Instrumental analysis .....	33
11.6 Estimation of detection and quantification limits .....	36
11.7 Quality control .....	37
11.8 Measurement uncertainty .....	38
12 Expression of results .....	38
12.1 Calculation of the volume of air samples .....	38
12.2 Calculation of mercury in air concentrations .....	39
13 Method performance .....	39
13.1 General .....	39
13.2 Detection and quantification limits .....	39
13.3 Upper limits of the analytical range .....	40