

---

---

**Control charts —**  
**Part 2:**  
**Shewhart control charts**

*Cartes de contrôle —*

*Partie 2: Cartes de contrôle de Shewhart*



Reference number  
ISO 7870-2:2013(E)

© ISO 2013



**COPYRIGHT PROTECTED DOCUMENT**

© ISO 2013

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office  
Case postale 56 • CH-1211 Geneva 20  
Tel. + 41 22 749 01 11  
Fax + 41 22 749 09 47  
E-mail [copyright@iso.org](mailto:copyright@iso.org)  
Web [www.iso.org](http://www.iso.org)

Published in Switzerland

# Contents

	Page
Foreword .....	iv
Introduction .....	v
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms, definitions and symbols</b> .....	<b>1</b>
3.1 General .....	1
3.2 Symbols .....	1
<b>4 Nature of Shewhart control charts</b> .....	<b>3</b>
<b>5 Types of control charts</b> .....	<b>5</b>
5.1 Control charts where no pre-specified values are given .....	5
5.2 Control charts with respect to given pre-specified values .....	6
5.3 Types of variables and attributes control charts .....	6
<b>6 Variables control charts</b> .....	<b>7</b>
6.1 Mean ( $\bar{X}$ ) chart and range ( $R$ ) chart or mean ( $\bar{X}$ ) chart and standard deviation ( $s$ ) chart .....	8
6.2 Control chart for individuals ( $\bar{X}$ ) and control chart for moving ranges ( $R_m$ ) .....	9
6.3 Control charts for medians ( $\bar{X}$ ) .....	10
<b>7 Control procedure and interpretation for variables control charts</b> .....	<b>11</b>
7.1 Collect preliminary data .....	11
7.2 Examine the $s$ (or $R$ ) chart .....	11
7.3 Remove assignable causes and revise the chart .....	11
7.4 Examine the $\bar{X}$ chart .....	12
7.5 Ongoing monitoring of process .....	12
<b>8 Pattern tests for assignable causes of variation</b> .....	<b>12</b>
<b>9 Process control, process capability, and process improvement</b> .....	<b>13</b>
<b>10 Attributes control charts</b> .....	<b>15</b>
<b>11 Preliminary considerations before starting a control chart</b> .....	<b>17</b>
11.1 Choice of critical to quality (CTQ) characteristics describing the process to control .....	17
11.2 Analysis of the process .....	17
11.3 Choice of rational subgroups .....	17
11.4 Frequency and size of subgroups .....	18
11.5 Preliminary data collection .....	18
11.6 Out of control action plan .....	18
<b>12 Steps in the construction of control charts</b> .....	<b>18</b>
12.1 Determine data collection strategy .....	19
12.2 Data collection and computation .....	20
12.3 Plotting $\bar{X}$ chart and $R$ chart .....	20
<b>13 Caution with Shewhart control charts</b> .....	<b>20</b>
13.1 General caution .....	21
13.2 Correlated data .....	22
13.3 Use of alternative rule to the three-sigma rule .....	22
<b>Annex A (informative) Illustrative examples</b> .....	<b>24</b>
<b>Annex B (informative) Practical notices on the pattern tests for assignable causes of variation</b> .....	<b>42</b>
<b>Bibliography</b> .....	<b>44</b>