
**Plastics — Polyols for use in the production
of polyurethanes — Determination of
hydroxyl number by NIR spectroscopy**

*Plastiques — Polyols pour la production de polyuréthanes —
Détermination de l'indice d'hydroxyle par spectroscopie dans le
proche infrarouge*



Reference number
ISO 15063:2011(E)

© ISO 2011



COPYRIGHT PROTECTED DOCUMENT

© ISO 2011

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	1
4.1 General	1
4.2 Procedure employed	2
4.3 Limitations	2
5 Instrumentation	2
5.1 General	2
5.2 Light source and detector	3
5.3 Spectrometer	3
5.4 Sampling system	3
5.5 Software	3
6 Developing a calibration model	3
6.1 Selection of calibration materials	3
6.2 Reference method and reference values	4
6.3 Determining wavelength regions and pathlength	4
6.4 Reduction of sources of spectral variation	4
6.5 Multivariate mathematical treatments	5
6.6 Evaluating calibration models	5
7 Validation of a multivariate calibration model	5
8 Calibration transfer	6
9 Calibration quality control	6
10 Procedure	6
10.1 General	6
10.2 Calibration curve	6
10.3 Measurement	7
10.4 Illustrative results	7
11 Precision of NIR estimated values	7
12 Test report	7
Annex A (informative) Illustrative results	8
Annex B (informative) NIR spectral measurements	15
Annex C (informative) Spectrometers	16
Annex D (informative) Sampling systems	17
Annex E (informative) Selection of calibration materials	18
Annex F (informative) Multivariate analysis	20
Annex G (informative) Statistical tools used to optimize calibration models	22
Annex H (informative) Sources of calibration and analysis error	25
Annex I (informative) Monitoring the performance of the instrument and calibration model	26
Bibliography	27