

TECHNICAL  
REPORT

**ISO**  
**TR 13618**

First edition  
1993-11-01

---

---

**Code of practice for the safe operation of  
work-holding chucks used on lathes**

*Lignes directrices pour l'utilisation sûre des mandrins porte-pièce de tour*



Reference number  
ISO/TR 13618:1993(E)

## ISO/TR 13618:1993(E)

## Contents

	Page
1 Scope .....	1
2 Chuck grip.....	1
2.1 General .....	1
2.2 Forces applied to the chuck .....	1
2.3 Change of grip at speed .....	9
2.4 Achieving the required grip .....	11
2.5 Flexible workpieces .....	11
3 Maximum speed of the chuck.....	11
4 Balancing .....	11
5 Inertia loading imposed on the drive .....	13
6 Gravitational and cutting forces: effect on the machine .....	15
7 Other aspects of the safe operation of lathe chucks.....	15
7.1 Chuck keys.....	15
7.2 Gross overspeeding .....	15
7.3 Adaptors .....	15
7.4 Mounting bolts for chuck body .....	15
7.5 Mounting bolts for jaws.....	15
7.6 Jaw materials.....	16
7.7 Dissipation of kinetic energy .....	16
7.8 Stroke detectors.....	16
7.9 End of bar detectors .....	16

© ISO 1993

All rights reserved. No part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization  
Case postale 56 • CH-1211 Genève 20 • Switzerland

Printed in Switzerland

<b>8</b>	Summary of the responsibilities of machine tool manufacturer, chuck manufacturer and user.....	16
----------	--	----

**Appendices**

<b>A</b>	Estimation of power available at the cutting zone .....	18
<b>B</b>	Radial stiffness and out-of-roundness of ring held in jaws .....	18
<b>C</b>	Measurement of the inertia of irregular components.....	19
<b>D</b>	Worked example .....	37
<b>E</b>	Bibliography.....	52