
Control charts —

Part 2: Shewhart control charts

Cartes de contrôle —

Partie 2: Cartes de contrôle de Shewhart





COPYRIGHT PROTECTED DOCUMENT

© ISO 2023

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland

Contents

Page

Foreword.....	v
Introduction.....	vi
1 Scope.....	1
2 Normative references.....	1
3 Terms and definitions.....	1
3.1 General presence.....	1
3.2 Symbols.....	1
3.2.1 For the purposes of this document, the following symbols apply.....	1
4 Concepts of Shewhart control charts.....	3
4.1 Shewhart control chart.....	3
4.2 Control limits.....	3
4.3 Process in statistical control.....	3
4.4 Action limits.....	4
4.5 Warning limits.....	4
4.6 Type 1 error.....	4
4.7 Type 2 error.....	4
4.8 Process not in control.....	4
4.9 Phase 1 of statistical process control.....	5
4.10 Phase 2 of control charts.....	5
5 Types of control charts.....	5
5.1 Types of Shewhart control charts.....	5
5.2 Control charts where no pre-specified values of process parameters are given.....	5
5.3 Control charts with respect to given pre-specified values of process parameters.....	6
5.4 Types of variables and attribute control charts.....	6
5.4.1 Variables control charts.....	6
5.4.2 Attribute control charts.....	6
6 Variables control charts.....	7
6.1 Usefulness of variables control charts.....	7
6.2 Assumption of normality.....	7
6.3 Pair of control charts.....	8
6.4 Average, $\bar{X}$ chart and range, R chart or average, $\bar{X}$ chart and standard deviation, s chart.....	8
6.5 Control chart for individuals, X_i , and moving ranges, R_m	9
6.6 Control charts for medians, $\tilde{X}$	10
7 Control procedure and interpretation for variables control charts.....	11
7.1 Underlying principle.....	11
7.2 Collect preliminary data.....	11
7.3 Examine s (or R) chart.....	11
7.4 Homogenization for s (or R) chart.....	11
7.5 Homogenization for $\bar{X}$ chart.....	12
7.6 Ongoing monitoring of process.....	12
8 Unnatural pattern and tests for assignable causes of variation.....	12
8.1 Natural pattern.....	12
8.2 Unnatural patterns.....	13
8.2.1 General.....	13
8.2.2 Lack of control in the average chart only.....	13
8.2.3 Lack of control in the variation chart only.....	13
8.2.4 Lack of control in both average and variation charts.....	14
8.2.5 Depiction of unnatural patterns.....	14
9 Process control, process capability, and process improvement.....	15