
**Workplace air — Determination
of mercury and inorganic mercury
compounds — Method by cold-vapour
atomic absorption spectrometry or
atomic fluorescence spectrometry**

*Air des lieux de travail — Détermination du mercure et des
composés inorganiques de mercure — Méthode par spectrométrie
d'absorption atomique ou spectrométrie de fluorescence atomique
de la vapeur froide*





COPYRIGHT PROTECTED DOCUMENT

© ISO 2015, Published in Switzerland

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Ch. de Blandonnet 8 • CP 401
CH-1214 Vernier, Geneva, Switzerland
Tel. +41 22 749 01 11
Fax +41 22 749 09 47
copyright@iso.org
www.iso.org

Contents

	Page
Foreword	vi
Introduction	vii
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
3.1 General definitions.....	2
3.2 Particle size fraction definitions.....	3
3.3 Sampling definitions.....	3
3.4 Analytical definitions.....	4
3.5 Statistical terms.....	6
4 Principle	7
5 Interferences	7
6 Requirement	8
7 Reagents	8
8 Apparatus	10
8.1 Sampling equipment for diffusive sampling.....	10
8.2 Sampling equipment for pumped sampling.....	11
8.3 Laboratory apparatus.....	14
8.4 Analytical instrumentation.....	16
9 Occupational exposure assessment	21
9.1 General.....	21
9.2 Personal sampling.....	21
9.3 Static (area) sampling.....	21
9.4 Selection of measurement conditions and measurement pattern.....	22
9.4.1 General.....	22
9.4.2 Screening measurements of variation of concentration in time and/or space.....	22
9.4.3 Screening measurements of time-weighted average concentration and worst case measurements.....	22
9.4.4 Measurements near an emission source.....	22
9.4.5 Measurements for comparison with limit values and periodic measurements.....	22
10 Sampling	23
10.1 Selection of sampling method.....	23
10.1.1 Measurement of mercury vapour.....	23
10.1.2 Measurement of particulate inorganic mercury compounds.....	23
10.1.3 Measurement of mercury vapour and particulate inorganic mercury compounds.....	23
10.2 Consideration of temperature and pressure effects.....	24
10.2.1 Effect of temperature and pressure on the uptake rate of diffusive badges.....	24
10.2.2 Effect of temperature and pressure on volumetric flow rate in the pumped sampling method.....	24
10.2.3 Expression of results.....	24
10.3 Diffusive sampling.....	24
10.3.1 Selection and use of diffusive badges.....	24
10.3.2 Preparation for sampling.....	25
10.3.3 Sampling position.....	26
10.3.4 Sample collection.....	26
10.3.5 Transportation of samples.....	26
10.4 Pumped sampling.....	27
10.4.1 Preliminary considerations.....	27
10.4.2 Preparation for sampling.....	28