

First edition
2018-03

**Fire test procedures for divisional
elements that are typically used in oil,
gas and petrochemical industries —**

**Part 1:
General requirements**

*Méthodes d'essais au feu des éléments de séparation habituellement
utilisés dans les industries pétrolières, gazières et pétrochimiques —*

Partie 1: Exigences générales



Reference number
ISO 20902-1:2018(E)



COPYRIGHT PROTECTED DOCUMENT

© ISO 2018

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Fax: +41 22 749 09 47
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland

Contents

	Page
Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	2
5 Test specimen	2
5.1 General	2
5.2 Vertical divisional element dimensions	2
5.3 Horizontal divisional element dimensions	5
5.4 Design	5
5.5 Description	5
5.6 Material specification	5
5.7 Control measurements	6
5.7.1 Thickness	6
5.7.2 Density	6
5.8 Conditioning	6
5.8.1 General	6
5.8.2 Verification	6
5.9 Mounting of test specimens	7
5.10 Examination of the test specimen	7
6 Instrumentation	7
6.1 General	7
6.2 Ambient temperature thermocouple	8
6.3 Furnace temperature thermocouples	8
6.3.1 Design	8
6.3.2 Number	8
6.3.3 Positioning	8
6.4 Furnace pressure sensors	8
6.5 Unexposed-face temperature thermocouples	8
6.5.1 Design	8
6.5.2 Preparation of surfaces to receive thermocouples	9
6.5.3 Fixing of thermocouples	9
6.6 Positioning of thermocouples on the specimen	10
6.6.1 General	10
6.6.2 Structural core temperature thermocouples	10
6.6.3 Stiffeners	11
6.6.4 Unexposed face thermocouples	11
6.7 Measuring and recording equipment for thermocouples	12
6.8 Cotton-wool pads	12
6.9 Gap gauges	12
6.10 Infrared camera	12
7 Test method	12
7.1 General	12
7.2 Commencement of the test	12
7.3 Ambient conditions	13
7.4 Furnace control	13
7.4.1 Furnace temperature	13
7.4.2 Time-temperature relationship	13
7.4.3 Permitted deviations	13
7.4.4 Furnace pressure	13
7.5 Measurements and observations on the test specimen	13