
**Sampling procedures for inspection
by variables —**

Part 2:

**General specification for single sampling
plans indexed by acceptance quality limit
(AQL) for lot-by-lot inspection of
independent quality characteristics**

Règles d'échantillonnage pour les contrôles par mesures —

*Partie 2: Spécification générale pour les plans d'échantillonnage
simples, indexés d'après la limite d'acceptation de qualité (LAQ), pour
les contrôles lot par lot des caractéristiques de qualité indépendantes*



PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.

© ISO 2006

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword.....	v
Introduction	vii
1 Scope	1
2 Normative references	1
3 Terms and definitions.....	2
4 Symbols	6
5 Acceptance quality limit (AQL).....	8
6 Switching rules for normal, tightened and reduced inspection	9
7 Relationship to ISO 2859-1 and ISO 3951-1	11
8 Consumer protection.....	12
9 Planning	13
10 Choice between variables and attributes	13
11 Choice between the “s” and “σ” methods	14
12 Choice of inspection level and AQL	14
13 Choice of sampling scheme	15
14 Preliminary operations	17
15 Standard univariate “s” method procedures.....	17
16 Standard multivariate “s” method procedures for independent quality characteristics.....	26
17 Standard univariate “σ” method procedures.....	28
18 Standard multivariate “σ” method procedures for independent quality characteristics	31
19 Standard multivariate combined “s” and “σ” method procedures for independent quality characteristics.....	32
20 Procedure during continuing inspection	34
21 Normality and outliers	34
22 Records.....	34
23 Operation of switching rules	35
24 Discontinuation and resumption of inspection	36
25 Switching between the “s” and “σ” methods	36
Annex A (normative) Tables for determining the appropriate sample size	37
Annex B (normative) Form <i>k</i> single sampling plans for the “s” method	39
Annex C (normative) Form <i>k</i> single sampling plans for the “σ” method.....	43
Annex D (normative) Values of f_s for maximum sample standard deviation (MSSD)	47
Annex E (normative) Values of f_{σ} process standard deviation	51
Annex F (normative) Estimating the process fraction nonconforming for sample size 3: “s” method	54