

BS 7996:2009



BSI British Standards

Torque measuring devices – Calibration and classification using continual torque application – Method

NO COPYING WITHOUT BSI PERMISSION EXCEPT AS PERMITTED BY COPYRIGHT LAW

raising standards worldwide™

Publishing and copyright information

The BSI copyright notice displayed in this document indicates when the document was last issued.

© BSI 2009

ISBN 978 0 580 53116 3

ICS 17.100

The following BSI references relate to the work on this standard:

Committee reference ISE/NFE/4

Draft for comment 09/30200283 DC

Publication history

First published September 2009

Amendments issued since publication

| Date | Text affected |
|------|---------------|
|------|---------------|

Contents

Foreword *iii*

- 1 Scope 1
- 2 Normative references 1
- 3 Terms, definitions, abbreviations and symbols 1
- 4 Preparation for calibration 4
- 5 Calibration procedure 9
- 6 Calculation of results 11
- 7 Classification of torque measuring devices 13
- 8 Calibration certificate 15

Annexes

- Annex A (informative) Orientation diagrams 16
- Annex B (informative) Method example of determining uncertainty of the calibration results of the torque measuring device 19
- Annex C (informative) Bandwidth 27

Bibliography 28

List of figures

- Figure A.1 – Continuous application of torque 16
- Figure A.2 – Example of preloading and calibration sequences for a torque measuring device with round shaft drives, six increasing and decreasing torques, classes 0.05 to 5.0 17
- Figure A.3 – Example of preloading and calibration sequences for a torque measuring device with round shaft drives, six increasing torques only, classes 0.05 to 5.0 17
- Figure A.4 – Example of preloading and calibration sequences for a torque measuring device with square drives, six increasing and decreasing torques, classes 0.05 to 5.0 17
- Figure A.5 – Example of preloading and calibration sequences for a torque measuring device with square drives, six increasing torques only, classes 0.05 to 5.0 17
- Figure A.6 – Example of preloading and calibration sequences for a torque measuring device, six increasing and decreasing torques, classes 0.2 to 5.0 18
- Figure A.7 – Example of preloading and calibration sequences for a torque measuring device, six increasing torques only, classes 0.2 to 5.0 18
- Figure B.1A – Worked example in torque units: 100 N·m torque measuring device clockwise torque, increasing series only 22
- Figure B.1B – Worked example in torque units: 100 N·m torque measuring device clockwise torque, increasing series only 22
- Figure B.1C – Worked example in torque units: 100 N·m torque measuring device clockwise torque, increasing series only 23
- Figure B.2 – Worked example in torque units: Expanded uncertainty as a function of applied torque 23
- Figure B.3 – Worked examples in torque units: Deviation as a function of applied torque 23
- Figure B.4A – Worked example in mV/V: 2 kN·m torque measuring device clockwise torque, increasing and decreasing series 24
- Figure B.4B – Worked example in mV/V: 2 kN·m torque measuring device clockwise torque, increasing and decreasing series 25
- Figure B.4C – Worked example in mV/V: 2 kN·m torque measuring device clockwise torque, increasing and decreasing series 25
- Figure B.5 – Worked example in mV/V: Expanded uncertainty as a function of applied torque 26
- Figure B.6 – Worked example in mV/V: Deviation as a function of applied torque 26