International Standard



4677/1

## Atmospheres for conditioning and testing – Determination of relative humidity – Part 1: Aspirated psychrometer method

Atmosphères de conditionnement et d'essai — Détermination de l'humidité relative — Partie 1: Méthode utilisant un psychromètre à aspiration

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION MEX DY APODHAR OPPAHUSALUR TO CTAHDAPTUSALUNGORGANISATION INTERNATIONALE DE NORMALISATION

First edition - 1985-10-15

UDC 620.1:551.584.6:533.275

Ref. No. ISO 4677/1-1985 (E)

Descriptors : standard atmosphere, test atmospheres, determination, humidity, psychrometers.

## Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work.

Draft International Standards adopted by the technical committees are circulated to the member bodies for approval before their acceptance as International Standards by the ISO Council. They are approved in accordance with ISO procedures requiring at least 75 % approval by the member bodies voting.

International Standard ISO 4677/1 was prepared by Technical Committee ISO/TC 125, *Enclosures and conditions for testing*.

Users should note that all International Standards undergo revision from time to time and that any reference made herein to any other International Standard implies its latest edition, unless otherwise stated.

## © International Organization for Standardization, 1985 •

Printed in Switzerland

## Contents

			Page	
0	Introduction 1			
1	Scope and field of application 1			
	1.1	Scope	1	
	1.2	Field of application	2	
2	Refe	References		
3	Definitions		2	
4	Principle		2	
5	Apparatus and materials		2	
	5.1	Thermometers	2	
	5.2	Wet-bulb covering, wick and water reservoir	3	
	5.3	Water	4	
	5.4	Air	4	
	5.5	Radiation shields	4	
6	Proc	zedure	4	
	6.1	Location	4	
	6.2	Preparation for test	4	
	6.3	Ventilation and observation	4	
7	Exp	ression of results	5	
	7.1	Determination from a psychrometric table or chart	5	
	7.2	Determination by calculation	5	
8	Acc	uracy	5	
9	Tes	t report	5	
Annexes				
A	Specification for mercury-in-glass thermometers which may be used when the dry-bulb temperature does not exceed 40 °C and the uncertainty in the value obtained for the relative humidity is not to exceed $\pm$ 3 % r.h.		6	
В	Procedure for determining the minimum distance for which the wet-bulb covering shall extend onto the thermometer stem to meet the requirement of 5.2.3.		8	
С	Ske	eleton table of relative humidities	9	
Bibliography				