

# HB

## 中华人民共和国航空工业标准

HB 6785~6816-93

---

### 气动量仪用测具及其零件








1994-06-01 发布








1994-06-01 实施

---

中国航空工业总公司 批准

# 目 录

| 序号 | 标准号        | 名 称                                          | 简 图                                                                                  | 页次 |
|----|------------|----------------------------------------------|--------------------------------------------------------------------------------------|----|
| 1  | HB 6785-93 | 2000 倍气动量仪用<br>内径测量头<br>( $D > 10 \sim 18$ ) |    | 1  |
| 2  | HB 6786-93 | 2000 倍气动量仪用<br>内径测量头<br>( $D > 18 \sim 24$ ) |    | 3  |
| 3  | HB 6787-93 | 2000 倍气动量仪用<br>内径测量头<br>( $D > 24 \sim 65$ ) |    | 5  |
| 4  | HB 6788-93 | 2000 倍气动量仪用<br>内径测量头<br>( $D > 65 \sim 80$ ) |   | 7  |
| 5  | HB 6789-93 | 5000 倍气动量仪用<br>内径测量头<br>( $D > 3 \sim 10$ )  |  | 9  |
| 6  | HB 6790-93 | 5000 倍气动量仪用<br>内径测量头<br>( $D > 10 \sim 18$ ) |  | 11 |
| 7  | HB 6791-93 | 5000 倍气动量仪用<br>内径测量头<br>( $D > 18 \sim 24$ ) |  | 13 |

| 序号 | 标准号        | 名称                                                        | 简图                                                                                   | 页次 |
|----|------------|-----------------------------------------------------------|--------------------------------------------------------------------------------------|----|
| 8  | HB 6792-93 | 5000 倍气动量仪用<br>内径测量头<br>( $D > 24 \sim 65$ )              |    | 15 |
| 9  | HB 6793-93 | 5000 倍气动量仪用<br>内径测量头<br>( $D > 65 \sim 80$ )              |    | 17 |
| 10 | HB 6794-93 | 5000 倍气动量仪用<br>带定位台阶<br>内径测量头<br>( $D \geq 8 \sim 14$ )   |    | 19 |
| 11 | HB 6795-93 | 5000 倍气动量仪用<br>带定位台阶<br>内径测量头<br>( $D > 14 \sim 30$ )     |   | 22 |
| 12 | HB 6796-93 | 5000 倍气动量仪用<br>带定位台阶盲孔<br>内径测量头<br>( $D \geq 8 \sim 14$ ) |  | 25 |
| 13 | HB 6797-93 | 5000 倍气动量仪用<br>带定位台阶盲孔<br>内径测量头<br>( $D > 14 \sim 30$ )   |  | 28 |
| 14 | HB 6798-93 | 10000 倍气动量仪用<br>内径测量头<br>( $D > 3 \sim 10$ )              |  | 31 |